
















# PRODUCT CATALOGUE

















---

## MERCEDES BENZ ACTROS MP3



<b>Item No:</b>	<b>Pictures</b>	<b>Des.</b>	<b>OE</b>
<b>SUP-BP3001-1R</b>		<b>Head light cover RH</b>	<b>9438260359</b>
<b>SUP-BP3001-1L</b>		<b>Head lights cover LH</b>	<b>9438260259</b>
<b>SUP-BP3002</b>		<b>grille</b>	<b>9437501418</b>
<b>SUP-BP3002-1</b>		<b>grille</b>	<b>9437501518</b>
<b>SUP-BP3003R</b>		<b>grille upper RH</b>	<b>9437514318</b>
<b>SUP-BP3003L</b>		<b>grille upper LH</b>	<b>9437514118</b>
<b>SUP-BP3004R</b>		<b>grille lower RH</b>	<b>9437514418</b>
<b>SUP-BP3004L</b>		<b>grille lower LH</b>	<b>9437514218</b>
<b>SUP-BP3005R</b>		<b>corner bumper RH</b>	<b>9438800370</b>
<b>SUP-BP3005L</b>		<b>corner bumper LH</b>	<b>9438800270</b>
<b>SUP-BP3006R</b>		<b>corner bumper RH</b>	<b>9438800770 9438800173</b>
<b>SUP-BP3006L</b>		<b>corner bumper LH</b>	<b>9438800670 9438800073</b>
<b>SUP-BP3007</b>		<b>bumper center</b>	<b>9438850201 9438850001</b>

<b>SUP-BP3008R</b>		<b>corner bumper RH</b>	<b>9438807570</b>
<b>SUP-BP3008L</b>		<b>corner bumper LH</b>	<b>9438807470 9438809870</b>
<b>SUP-BP3009R</b>		<b>corner bumper RH</b>	<b>9438800104 9438804573</b>
<b>SUP-BP3009L</b>		<b>corner bumper LH</b>	<b>9438800004 9438804473</b>
<b>SUP-BP3010</b>		<b>bumper center</b>	<b>9438850426 9438850226</b>
<b>SUP-BP3011R</b>		<b>corner panel RH</b>	<b>9438842022</b>
<b>SUP-BP3011L</b>		<b>corner panel LH</b>	<b>9438841922</b>
<b>SUP-BP3012R</b>		<b>inner corner panel RH</b>	<b>9438841822</b>
<b>SUP-BP3012L</b>		<b>inner corner panel LH</b>	<b>9438841722</b>
<b>SUP-BP3013R</b>		<b>cover RH</b>	<b>9438840174</b>
<b>SUP-BP3013L</b>		<b>cover LH</b>	<b>94388400074</b>
<b>SUP-BP3014</b>		<b>cover</b>	<b>9438850374</b>
<b>SUP-BP3015R</b>		<b>cover RH</b>	<b>9438850163</b>
<b>SUP-BP3015L</b>		<b>cover LH</b>	<b>9438850063</b>
<b>SUP-BP3016</b>		<b>bumper center</b>	<b>9438850301 9438850101</b>

<b>SUP-BP3017R</b>		<b>cover RH</b>	<b>9438840060</b>
<b>SUP-BP3017L</b>		<b>cover LH</b>	<b>9438840160</b>
<b>SUP-BP3018R</b>		<b>dirt deflector RH</b>	<b>9438851225</b>
<b>SUP-BP3018L</b>		<b>dirt deflector LH</b>	<b>9438851125</b>
<b>SUP-BP3019</b>		<b>dirt deflector</b>	<b>9438851325</b>
<b>SUP-BP3019-1</b>		<b>dirt deflector</b>	<b>9438851825</b>
<b>SUP-BP3020R</b>		<b>dirt deflector RH</b>	<b>9438851322</b>
<b>SUP-BP3020L</b>		<b>dirt deflector LH</b>	<b>9438851222</b>
<b>SUP-BP3021R</b>		<b>dirt deflector RH</b>	<b>9438851725</b>
<b>SUP-BP3021L</b>		<b>dirt deflector LH</b>	<b>9438851625</b>
<b>SUP-BP3022R</b>		<b>cover RH</b>	<b>9438851522</b>
<b>SUP-BP3022L</b>		<b>cover LH</b>	<b>9438851422</b>
<b>SUP-BP3023R</b>		<b>cover RH</b>	<b>9438851022</b>
<b>SUP-BP3023L</b>		<b>cover LH</b>	<b>9438850922</b>
<b>SUP-BP3024</b>		<b>cover</b>	<b>9438851122</b>
<b>SUP-BP3025</b>		<b>sunvisor with hole</b>	<b>9438100910</b>

<b>SUP-BP3026</b>		<b>sunvisor without hole</b>	<b>9438100810</b>
<b>SUP-BP3026-1</b>		<b>bumper step</b>	<b>9438850526</b>
<b>SUP-BP3027</b>		<b>air filter housing</b>	<b>0180946302 0040942404</b>
<b>SUP-BP3028</b>		<b>air filter housing cover</b>	<b>0180946302 0040942404</b>
<b>SUP-BP3029R</b>		<b>mirror complete RH</b>	<b>9438110407 9438106016</b>
<b>SUP-BP3029L</b>		<b>mirror complete LH</b>	<b>9438110307 9438105616</b>
<b>SUP-BP3030</b>		<b>wide angle mirror</b>	<b>9438105116</b>
<b>SUP-BP3031</b>		<b>steel panel</b>	<b>9437500109</b>
<b>SUP-BP3032R</b>		<b>extension board RH</b>	<b>9438800236</b>
<b>SUP-BP3032L</b>		<b>extension board LH</b>	<b>9438800136</b>
<b>SUP-BP3033R</b>		<b>extension board RH</b>	<b>9438801436</b>
<b>SUP-BP3033L</b>		<b>extension board LH</b>	<b>9438801336</b>

<b>SUP-BP3034R</b>		<b>extension board RH</b>	<b>9438800436</b>
<b>SUP-BP3034L</b>		<b>extensioin board LH</b>	<b>9438800336</b>
<b>SUP-BP3035</b>		<b>oil sump</b>	<b>5410140902</b>
<b>SUP-BP3036R</b>		<b>corner bumper RH</b>	<b>9438850322</b>
<b>SUP-BP3036L</b>		<b>corner bumper LH</b>	<b>9438850222</b>
<b>SUP-BP3037R</b>		<b>bumper bracket RH</b>	<b>9436660578</b>
<b>SUP-BP3037L</b>		<b>bumper bracket LH</b>	<b>9436660478</b>
<b>SUP-BP3038R</b>		<b>bumper bracket RH</b>	<b>9436660778</b>
<b>SUP-BP3038L</b>		<b>bumper bracket LH</b>	<b>9436660678</b>
<b>SUP-BP3039R</b>		<b>bracket RH</b>	<b>9436661031</b> <b>9436662631</b>
<b>SUP-BP3039L</b>		<b>bracket LH</b>	<b>9436660931</b> <b>9436662531</b>
<b>SUP-BP3040R</b>		<b>bracket RH</b>	<b>9436660831</b> <b>94366601231</b>
<b>SUP-BP3040L</b>		<b>bracket LH</b>	<b>9436660731</b> <b>9436661131</b>
<b>SUP-BP3041R</b>		<b>bracket RH</b>	<b>94366600531</b> <b>94366601831</b>

<b>SUP-BP3041L</b>		<b>bracket LH</b>	<b>9436600431 9436601731</b>
<b>SUP-BP3042</b>		<b>grille brackets complete</b>	<b>9437500168 RH 9437500068 LH 9437510116 MIDDLE</b>
<b>SUP-BP3043</b>		<b>sunvisor brackets complete</b>	<b>9438101714</b>
<b>SUP-BP3044</b>		<b>grille</b>	<b>9438851822</b>



[WWW.SUPREMETRUCKEL.CO.ZA](http://WWW.SUPREMETRUCKEL.CO.ZA)

[INFO@SUPREMETRUCKEL.CO.ZA](mailto:INFO@SUPREMETRUCKEL.CO.ZA)

0437311032

